


12. WIRING DIAGRAMS V45 SABRE (VF750S)



COMB. SW.					TIME				SELECT				TURN SIGNAL				DIMMER				HORN		ENGINE STOP		STARTER											
OFF	BAT	IGN	TL ₁	PA	FREE	T	E	FREE	S	E	FREE	R	W	R	L	P ₁	P ₂	P _L	LO	HL	LO	HL	FREE	H ₀	BAT ₁	OFF	IGN	BAT ₂	FREE	ST	BAT ₁	HL	BAT ₂			
○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○

B1-BLACK B2-BROWN
 Y-YELLOW O-ORANGE
 BU-BLUE LB-LIGHT BLUE
 G-GREEN LG-LIGHT GREEN
 R-RED P-PINK
 W-WHITE GR-GRAY